



VEHICLE INSPECTION REPORT

KN68ZST

Citroen C4 Spacetourer 1.5 BlueHDi 130 Flair 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	28/09/2018	Keys	2	CAP Clean	£6,525.00
Year	2018	Service history	Yes	CAP Average	£5,700.00
Mileage	79,537 Miles Warranted	Service documents	Service Book	CAP Below	£4,850.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	BLACK	Last service date	24/05/2025	Gears	6
VIN	VF73DYHZPJ803729	Last service miles	74,255		
Body Style	MPV	MOT Due	02/10/2025		

£65 ADDITIONAL FEE

Last service 24/05/2025 at 74,255 miles- 7 services

Tyres

NSF	POWERTRAC	5.0mm
NSR	THREEA	5.0mm
OSF	POWERTRAC	5.0mm
OSR	THREEA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Partial leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Dented
With Paint Damage



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
Between 10mm + 30mm



14: Wheel nsf
Scratched
Over 50mm



15: Wing osf
Scratched
UpTo 25mm Thru Paint



16: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK