



VEHICLE INSPECTION REPORT

GX73WVU

Volkswagen T-Roc 1.5 TSI Style 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	19/09/2023	Keys	2	CAP Average	£20,100.00
Year	2023	Service history	Yes	CAP Below	£18,700.00
Mileage	19,353 Miles Warranted	Service documents	Printout	Gearbox	SEMI AUTO
Fuel Type	Petrol	Number of stamps	3	Gears	7
Colour	BLACK	Last service date	24/07/2025	Doors	5
VIN	WVGZZZA1ZRV006362	Last service miles	18,166		
Body Style	Hatchback	CAP Clean	£21,500.00		

£65 ADDITIONAL FEE

Last service 24/07/2025 at 18,166 miles- 3 main dealer services

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Wheel nsr
Scratched
Up To 50mm

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsr
Scratched
Over 25mm Not Thru Paint



8: Wheel nsr
Scratched
Up To 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

10: Bumper Rear
Chipped
Multiple Chips

No Image



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

12: Wheel osr
Scratched
Up To 50mm

No Image

No Image

13: Door osr
Scratched
Over 25mm Not Thru Paint

14: Door osf
Scratched
Over 25mm Not Thru Paint

No Image

15: Wing osf
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK