



VEHICLE INSPECTION REPORT

VX64XLK

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 5dr DSG

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
3

Details

Reg. date 29/09/2014

Year 2014

Mileage 72,866 Miles
Warranted

Fuel Type Diesel

Colour BEIGE

VIN WVGZZZ5NZFW027420

Body Style Estate

Keys 2

MOT Due 15/08/2026

CAP Clean £6,000.00

CAP Average £5,200.00

CAP Below £4,375.00

Gearbox SEMI AUTO

Gears 7

£65 ADDITIONAL FEE

Tyres

NSF MARSHAL 3.0mm

NSR MARSHAL 5.0mm

OSF MARSHAL 4.0mm

OSR MARSHAL 4.0mm

Spare

Features


- Bluetooth connection
- PAS
- Radio/CD
- Air conditioning
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint

No Image

4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Up To 50mm

No Image

10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Bumper Rear
Chipped
Multiple Chips

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image

13: Boot Lid
Scratched
Over 25mm Not Thru Paint

No Image

14: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



15: Wheel osr
Scratched
Up To 50mm



16: Door osr
Chipped
1 To 5



17: Door osf
Dented
With Paint Damage



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK