



46 Brampton Road  
Eastbourne  
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**HX64ZNP**

## Volvo XC60 D5 [215] R DESIGN Lux Nav 5dr AWD Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	25/09/2014	Keys	2	CAP Clean	£8,625.00
Year	2014	Service history	Yes	CAP Average	£7,625.00
Mileage	84,688 Miles Warranted	Service documents	Service Book	CAP Below	£6,625.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	AUTOMATIC
Colour	SILVER	Last service date	06/09/2023	Gears	6
VIN	YV1DZ8256F2652753	Last service miles	70,635		
Body Style	Estate	MOT Due	24/09/2025		

£65 ADDITIONAL FEE

Last service 06/09/2023 at 70,635 miles- 8 services (7 main dealer)

### Tyres

NSF	PIRELLI	2.0mm
NSR	PIRELLI	3.0mm
OSF	PIRELLI	2.0mm
OSR	PIRELLI	2.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Side airbags
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5



6: Door nsr  
Chipped  
1 To 5

No Image



7: Door nsf  
Scratched  
Over 25mm Not Thru Paint

8: Door nsr  
Chipped  
1 To 5

No Image

9: Door nsr  
Scratched  
Over 25mm Not Thru Paint



10: Qtr Panel nsr  
Chipped  
1 To 5

No Image

11: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



12: Wheel nsr  
Scratched  
Over 50mm



13: Bumper Rear  
Poor Previous Repair  
Poor Paint



14: Boot Lid  
Dented  
Over 2 UpTo 10mm





15: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



16: Wheel osr  
Scratched  
Up To 50mm



17: Door osr  
Chipped  
1 To 5



18: Door osr  
Scratched  
Over 25mm Not Thru Paint



19: Door osf  
Chipped  
1 To 5



20: Door osf  
Scratched  
Over 25mm Not Thru Paint



21: Wing osf  
Chipped  
1 To 5



22: Wheel osf  
Scratched  
Over 50mm



23: Door osf  
Dented  
Between 10mm + 30mm

Interior

Carpet Condition      Average  
Seat Condition      Average

Upholstery Condition      Average  
Odour      No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK