



# VEHICLE INSPECTION REPORT

**EY11GME**

## Audi TT 2.0 TDI Quattro Black Edition 2dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama  
GRADE  
**3**

### Details

Reg. date	22/07/2011	VIN	TRUZZZ8J7B1024927	CAP Average	£3,200.00
Year	2011	Body Style	Coupe	CAP Below	£2,675.00
Mileage	88,727 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	22/08/2026	Gears	6
Colour	GREY	CAP Clean	£3,725.00		

£65 ADDITIONAL FEE. Suspension knocking sound and noise while driving


### Tyres

NSF	GENERAL TIRE	4.0mm
NSR	GENERAL TIRE	4.0mm
OSF	GENERAL TIRE	4.0mm
OSR	GENERAL TIRE	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- Passenger airbag
- Alloy wheels
- PAS
- Radio/CD
- Climate control
- Metallic Paint
- Central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- ABS
- Remote central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Drivers airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips



No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wing nsf  
Chipped  
1 To 5

No Image

5: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Wheel nsf  
Scratched  
Over 50mm



7: Door nsr  
Chipped  
1 To 5

No Image

8: Door nsf  
Scratched  
UpTo 25mm Not Thru Paint

No Image



9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Chipped  
Multiple Chips

No Image

12: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



13: Boot Lid  
Dented  
Between 10mm + 30mm



14: Qtr Panel osr  
Chipped  
1 To 5



No Image



15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osr  
Scratched  
Over 50mm



17: Door osf  
Chipped  
1 To 5

No Image

18: Door osf  
Scratched  
Over 25mm Not Thru Paint



19: Wing osf  
Dented  
With Paint Damage



20: Wheel osf  
Scratched  
Over 50mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK