

# VEHICLE INSPECTION REPORT

**LV64YFP**

## Nissan Juke 1.6 Acenta Premium 5dr Xtronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
**3**

### Details

Reg. date	30/11/2014	VIN	SJNFBAF15U7057947	CAP Average	£3,950.00
Year	2014	Body Style	Hatchback	CAP Below	£3,325.00
Mileage	55,443 Miles Warranted	Keys	2	Gearbox	CVT
Fuel Type	Petrol	MOT Due	10/01/2026	Gears	5
Colour	BLACK	CAP Clean	£4,575.00	Doors	5



### Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	Worn
OSF	BUDGET	2.0mm
OSR	BUDGET	3.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Poor Previous Repair  
Poor Paint



2: Boot Lid  
Chipped  
1 To 5



No Image



3: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

4: Qtr Panel osr  
Chipped  
1 To 5

No Image



5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

6: Wheel osr  
Scratched  
Up To 50mm




7: Door osr  
Dented  
Over 2 UpTo 10mm

No Image

8: Door osr  
Scratched  
Over 25mm Not Thru Paint



9: Door osf  
Chipped  
1 To 5




10: Door osf  
Scratched  
Over 25mm Not Thru Paint



11: Wing osf  
Chipped  
1 To 5



12: Wheel osf  
Scratched  
Over 50mm



13: Bonnet  
Chipped  
1 To 5



14: Bumper Front  
Chipped  
Multiple Chips



No Image



15: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

16: Wheel nsf  
Scratched  
Over 50mm



17: Wing nsf  
Chipped  
1 To 5

No Image

18: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



19: Door nsf  
Dented  
With Paint Damage



20: Door nsr  
Dented  
With Paint Damage




21: Wheel nsr  
Scratched  
Up To 50mm




22: Qtr Panel nsr  
Chipped  
1 To 5



23: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



24: Seat Base Cover osf  
Torn  
UpTo 3mm



25: Other  
N/A  
N/A

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK