



# VEHICLE INSPECTION REPORT

**GN65UKT**

## Mazda 3 2.0 SE-L 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama  
GRADE  
2

### Details

Reg. date	04/09/2015	Keys	2	CAP Clean	£4,525.00
Year	2015	Service history	Yes	CAP Average	£3,875.00
Mileage	69,734 Miles Warranted	Service documents	Printout	CAP Below	£3,200.00
Fuel Type	Petrol	Number of stamps	10	Gearbox	MANUAL
Colour	GREY	Last service date	03/10/2024	Gears	6
VIN	JMZBM646611305234	Last service miles	55,293	Doors	5
Body Style	Hatchback	MOT Due	09/10/2025		

LAST SERVICE 3/10/24 @ 55,293 MILES (10 SERVICES 7 MAIN DEALER) PRINT

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint

4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Dented  
Over 2 UpTo 10mm

No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Dented  
2 Or Less UpTo 10mm




10: Wheel nsr  
Scratched  
Over 50mm



11: Qtr Panel nsr  
Chipped  
1 To 5



12: Bumper Rear  
Chipped  
Multiple Chips



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint




14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint





15: Qtr Panel osr  
Dented  
Between 10mm + 30mm



16: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



17: Wheel osr  
Scratched  
Over 50mm



18: Door osr  
Dented  
Over 2 UpTo 10mm



19: Door osf  
Dented  
Over 2 UpTo 10mm



20: Wing osf  
Chipped  
1 To 5



21: Bumper Front  
Scratched  
25 to 100mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK