



VEHICLE INSPECTION REPORT

RK66EOF

Skoda Fabia 1.2 TSI 90 Monte Carlo 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	16/09/2016	Keys	2	CAP Clean	£4,200.00
Year	2016	Service history	Yes	CAP Average	£3,625.00
Mileage	95,263 Miles Warranted	Service documents	Printout	CAP Below	£3,025.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	SILVER	Last service date	16/09/2024	Gears	5
VIN	TMBFM6NJ1HZ019439	Last service miles	86,897	Doors	5
Body Style	Hatchback	MOT Due	16/09/2025		

LAST SERVICE 16/9/24 @ 86,897 MILES (3 SERVICES) PRINT

Tyres

NSF	DAVANTI	3.0mm
NSR	BUDGET	3.0mm
OSF	DAVANTI	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front electric windows
- Metallic Paint
- ESP
- Central locking
- PAS
- Digital radio
- Front fog lights
- Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- ABS
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5

No Image



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Chipped
1 To 5



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Dented
Over 2 UpTo 10mm



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Roof
Dented
Between 10mm + 30mm



17: Door osr
Chipped
1 To 5



18: Door osf
Poor Previous Repair
Poor Paint



19: Wing osf
Dented
Between 10mm + 30mm



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK