



# VEHICLE INSPECTION REPORT

RE66CVM

## BMW 2 Series 218i Luxury 5dr [Nav] Step Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	29/09/2016	VIN	WBA2A32040V463666	CAP Average	£7,675.00
Year	2016	Body Style	Hatchback	CAP Below	£6,675.00
Mileage	35,367 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
Fuel Type	Petrol	MOT Due	28/09/2025	Gears	6
Colour	BLUE	CAP Clean	£8,675.00	Doors	5

### Tyres

NSF	BUDGET	3.0mm
NSR	MICHELIN	3.0mm
OSF	FALKEN	3.0mm
OSR	MICHELIN	4.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos






## Condition Check



## Damage Photos



1: Bumper Front  
Cracked  
Over 25mm



2: Bonnet  
Chipped  
1 To 5





3: Wheel osf  
Scratched  
Over 50mm

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door osf  
Chipped  
1 To 5

No Image

6: Door osf  
Scratched  
Over 25mm Not Thru Paint

No Image

7: Door osr  
Scratched  
Over 25mm Not Thru Paint

No Image


8: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel osr  
Scratched  
Up To 50mm



10: Bumper Rear  
Chipped  
Multiple Chips



11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Scratched  
Over 25mm Not Thru Paint



13: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



14: Wheel nsr  
Scratched  
Up To 50mm



15: Door nsr  
 Scratched  
 Over 25mm Thru Paint



16: Door nsf  
 Dented  
 Over 2 UpTo 10mm



17: Wing nsf  
 Chipped  
 1 To 5



18: Wheel nsf  
 Scratched  
 Over 50mm

**Interior**

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

**Vehicle Inspection Report**

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK



EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK