



VEHICLE INSPECTION REPORT

AU18WCT

Ford Kuga 1.5 EcoBoost ST-Line 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/06/2018	Keys	2	CAP Clean	£6,175.00
Year	2018	Service history	Yes	CAP Average	£5,325.00
Mileage	79,296 Miles Warranted	Service documents	Service Book	CAP Below	£4,500.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	SILVER	Last service date	26/05/2022	Gears	6
VIN	WF0AXXWPMAS25774	Last service miles	31,283	Doors	5
Body Style	Hatchback	MOT Due	20/04/2026		

£100 ADDITIONAL FEE

Last service 26/05/2022 at 31,283 miles- 2 services (1 main dealer) Eml light is on
Engine tapping

Tyres

NSF	MATADOR	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Towbar
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Flasher Side Repeater ns
Broken
Replace



4: Door nsf
Chipped
1 To 5



5: Wheel nsr
Scratched
Over 50mm



6: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Tailgate
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Scratched
25 to 100mm Thru Paint



10: Wheel osr
Scratched
Up To 50mm




11: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



12: Door osr
Chipped
1 To 5



13: Door osf
Dented
2 Or Less UpTo 10mm



14: Wing osf
Chipped
1 To 5



15: Roof
Chipped
Over 5mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK