

VEHICLE INSPECTION REPORT

HY64XRA

Audi Q3 1.4T FSI SE 5dr

| Inspection | No | Vehicle | Margin | | nama |
|-----------------|------------------------|--------------------|------------|-------------|-----------|
| Serious Damage? | | VAT | | | 2 Grade |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 15/09/2014 | Body Style | Estate | MOT Due | Expired |
| Year | 2014 | Keys | 2 | CAP Clean | £6,150.00 |
| Mileage | 79,666 Miles Warranted | Service history | Yes | CAP Average | £5,300.00 |
| Fuel Type | Petrol | Service documents | Printout | CAP Below | £4,475.00 |
| Colour | BLACK | Last service date | 07/01/2025 | Gearbox | MANUAL |
| VIN | WAUZZZ8U2ER074108 | Last service miles | 78,214 | Gears | 6 |

£65 ADDITIONAL FEE Last service 07/01/2025 @ 78214 miles (10 MAIN DEALER SERVICES)

| Tyres |
|-------|
|-------|

| NSF | PIRELLI | 6.0mm |
|-------|---------|-------|
| NSR | PIRELLI | 5.0mm |
| OSF | PIRELLI | 2.0mm |
| OSR | PIRELLI | 6.0mm |
| Spare | | |

Features

- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

- PAS
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- · Drivers airbag
- Central locking
- · Rear parking sensor
- Audio remote control
- Air conditioning
- Front head restraints
- Solid Paint
- · Isofix child seat anchor points
- · Remote central locking
- · Rear wiper Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos






















Condition Check



Damage Photos



1: Bumper Rear Chipped Multiple Chips No Image

2: Bumper Rear Scratched Over 25mm Not Thru Paint



3: Boot Lid Chipped 1 To 5



4: Qtr Panel nsr Chipped 1 To 5



5: Wheel nsr Scratched Up To 50mm



6: Door nsr Scratched Over 25mm Thru Paint



7: Door nsf Chipped 1 To 5

No Image

8: Door nsf Scratched UpTo 25mm Not Thru Paint



9: Door Mirror Assy nsf Scratched (Painted) Over 25mm Thru Paint

No Image

10: Wing nsf Scratched Over 25mm Not Thru Paint



11: Wheel nsf Scratched Over 50mm



12: Bonnet Chipped 1 To 5



13: Wing Front Arch Extension ns Scratched (Painted) Over 25mm Thru Paint



14: Bumper Front ChippedMultiple Chips



15: Wing osf Chipped 1 To 5



16: Wheel osf Scratched Up To 50mm



17: Door osf Chipped 1 To 5



18: Door osr Scratched Over 25mm Not Thru Paint



19: Wheel osr Scratched Over 50mm

No Image

20: Qtr Panel osr Scratched Over 25mm Not Thru Paint

Interior

Carpet Condition Seat Condition

Average Average **Upholstery Condition Odour**

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
|--------------------------|----|--|----|
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |