



# VEHICLE INSPECTION REPORT

**GJ67HGZ**

## Vauxhall Mokka X 1.4T Active 5dr

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
5

### Details

Reg. date 18/09/2017

Year 2017

Mileage 72,825 Miles  
Warranted

Fuel Type Petrol

Colour RED

VIN W0LJC7E84HB228634

Body Style Hatchback

Keys 2

Service history Yes

Service documents Service Book

Number of stamps 4

Last service date 04/03/2023

Last service miles 51,891

MOT Due 28/06/2026

CAP Clean £3,600.00

CAP Average £3,050.00

CAP Below £2,500.00

Gearbox MANUAL

Gears 6

Doors 5

£65 ADDITIONAL FEE

Last service 04/03/2023 at 51,891 miles- 4 services

### Tyres

NSF BUDGET 5.0mm

NSR CONTINENTAL 3.0mm

OSF BUDGET 6.0mm

OSR RIKEN 6.0mm

Spare

## Features


- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Wheel nsf  
Scratched  
Over 50mm




4: Wing nsf  
Dented  
With Paint Damage



5: Door nsf  
Scratched  
Over 25mm Thru Paint



6: Door nsr  
Scratched  
Over 25mm Thru Paint



7: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint



9: Tailgate  
Scratched  
Over 25mm Thru Paint



10: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



11: Door osr  
Scratched  
Over 25mm Thru Paint



12: Wing osf  
Scratched  
UpTo 25mm Thru Paint




13: Door nsf  
Chipped  
Edge Chip



14: Wheel osf  
Scratched  
Up To 50mm





15: Roof  
Dented  
Over 30mm

16: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK