



VEHICLE INSPECTION REPORT

GP21ERJ

BMW 1 Series 118i [136] M Sport 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	24/07/2021	Keys	2	CAP Clean	£18,300.00
Year	2021	Service history	Yes	CAP Average	£17,100.00
Mileage	9,434 Miles Warranted	Service documents	Printout	CAP Below	£15,950.00
Fuel Type	Petrol	Number of stamps	2	Gearbox	MANUAL
Colour	BLUE	Last service date	16/07/2025	Gears	6
VIN	WBA7K320907J80624	Last service miles	8,815	Doors	5
Body Style	Hatchback	MOT Due	23/07/2026		

£65 ADDITIONAL FEE. Last service 16/07/2025 at 8815 miles (2 services (1 main dealer)).

Tyres

NSF	GOODYEAR	4.0mm
NSR	GOODYEAR	4.0mm
OSF	GOODYEAR	4.0mm
OSR	GOODYEAR	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- ESP
- Central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Bumper Rear
Scratched
Over 25mm Not Thru Paint

No Image



3: Boot Lid
Scratched
Over 25mm Not Thru Paint

4: Qtr Panel osr
Chipped
1 To 5



5: Wheel osr
Scratched
Up To 50mm



6: Door osr
Chipped
1 To 5

No Image



7: Door osf
Scratched
Over 25mm Not Thru Paint

8: Wing osf
Chipped
1 To 5



9: Wheel osf
Scratched
Up To 50mm




10: Bumper Front
Chipped
Multiple Chips



11: Wheel nsf
Scratched
Up To 50mm



12: Door nsf
Dented
2 Or Less UpTo 10mm



13: Door nsr
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



15: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK