

## **VEHICLE INSPECTION REPORT**

LD62TSU

## Volkswagen Golf 1.4 TSI Match 5dr DSG

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present	<u> </u>	
Details					
Reg. date	29/09/2012	Keys	2	CAP Clean	£4,075.00
Year	2012	Service history	Yes	CAP Average	£3,475.00
Mileage	72,952 Miles Warranted	Service documents	Service Book	CAP Below	£2,850.00
Fuel Type	Petrol	Number of stamps	13	Gearbox	SEMI AUTO
Colour	GREY	Last service date	09/06/2025	Gears	7
VIN	WVWZZZ1KZDP040250	Last service miles	71,791	Doors	5
Body Style	Hatchback	MOT Due	06/07/2026		

#### £65 ADDITIONAL FEE

Last service 09/06/2025 at 71,791 miles- 13 services (10 main dealer)

т	'n	r	6	S
	y		c	J

NSF	GOODYEAR	5.0mm	
NSR	GOODYEAR	5.0mm	
OSF	FIRESTONE	5.0mm	
OSR	GOODYEAR	5.0mm	
Spare			

### **Features**

- Bluetooth connection
- Rear parking sensor
  Body coloured bumpers
- Folding rear seats
  Height adjustable drivers seat
  3x3 point rear seat belts
  ESP

- Side airbags
- · Alloy wheels

- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Isofix child seat anchor points
- Central locking

- Front parking sensor Steering wheel mounted controls Front fog lights Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag Remote central locking
- PAS
- Digital radio
- Air conditioning
  Front head restraints
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim

#### **Photos**










# **Condition Check**



## **Damage Photos**



1: Tailgate Rusted UpTo 5mm



2: Bonnet Scratched Over 25mm Thru Paint



3: Bumper Front Dented With Paint Damage



4: Wheel nsf Scratched Over 50mm



5: Wing nsf Scratched Over 25mm Thru Paint



6: Door Mirror Assy nsf Scratched (Painted) UpTo 25mm Thru Paint



7: Door nsf Dented Over 30mm



8: Sill ns Dented Between 10mm + 30mm



9: Door nsr Scratched Over 25mm Thru Paint



10: Wheel nsr Scratched Over 50mm



11: Qtr Panel nsr Scratched UpTo 25mm Thru Paint



12: Bumper Rear Scratched 25 to 100mm Thru Paint



13: Qtr Panel osr Dented With Paint Damage



14: Wheel osr Scratched Over 50mm



15: Door osr Scratched UpTo 25mm Thru Paint



16: Door osf Chipped Edge Chip



17: Wheel osf Scratched Over 50mm

### Interior

Carpet Condition Seat Condition

Average Average Upholstery Condition Odour

Average No