



VEHICLE INSPECTION REPORT

EA66WWB

Volkswagen Tiguan 2.0 TDi 150 4Motion SE Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/10/2016	Keys	2	CAP Clean	£7,725.00
Year	2016	Service history	Yes	CAP Average	£6,750.00
Mileage	111,954 Miles Warranted	Service documents	Service Book	CAP Below	£5,825.00
Fuel Type	Diesel	Number of stamps	10	Gearbox	MANUAL
Colour	GREEN	Last service date	12/03/2025	Gears	6
VIN	WVGZZZ5NZHW843973	Last service miles	109,500		
Body Style	Estate	MOT Due	30/10/2025		

£65 ADDITIONAL FEE

Last service 12/03/2025 at 109,500 miles- 10 services (5 main dealer) book and print

Tyres


NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	3.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Chipped
1 To 5

No Image



4: Qtr Panel osr
Chipped
1 To 5

3: Boot Lid
Scratched
Over 25mm Not Thru Paint



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Dented
Over 2 UpTo 10mm

No Image



8: Door osf
Dented
Over 2 UpTo 10mm

7: Door osr
Scratched
Over 25mm Not Thru Paint

No Image



9: Door osf
Scratched
Over 25mm Not Thru Paint

10: Wing osf
Chipped
1 To 5



11: Wheel osf
Scratched
Over 50mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



13: Bumper Front
Scratched
Over 25mm Not Thru Paint

14: Bonnet
Chipped
1 To 5

No Image



15: Bonnet
Scratched
Over 25mm Not Thru Paint

16: Wheel nsf
Scratched
Up To 50mm



17: Door nsf
Dented
With Paint Damage



18: Door nsr
Chipped
1 To 5



19: Wheel nsr
Scratched
Over 50mm

No Image

20: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK