



VEHICLE INSPECTION REPORT

EA10GZL

Mazda 5 2.0 Takara 5dr Auto

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 TBC

nama
GRADE
5

Details

Reg. date 05/05/2010

VIN JMZCR19F700368813

CAP Average £810.00

Year 2010

Body Style MPV

CAP Below £400.00

Mileage 109,537 Miles
Warranted

Keys 2

Gearbox AUTOMATIC

Fuel Type Petrol

MOT Due Expired

Gears 5

Colour BLUE

CAP Clean £1,200.00

£65 ADDITIONAL FEE. Ns mirror noisy and gearbox notch
Suspension knocking

Tyres

NSF PIRELLI 3.0mm

NSR PIRELLI 4.0mm

OSF PIRELLI 4.0mm

OSR BRIDGESTONE 4.0mm

Spare

Features


- PAS
- Radio/CD
- Climate control
- Rear electric windows
- ABS
- Passenger airbag
- Alloy wheels
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Curtain airbags
- Central locking
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Metallic Paint
- Drivers airbag
- Remote central locking
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
With Paint Damage




5: Roof
Dented
Over 30mm



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Poor Previous Repair
Poor Paint



10: Wheel nsr
Scratched
Over 50mm




11: Bumper Rear
Chipped
Multiple Chips



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
With Paint Damage



18: Door osf
Dented
Over 30mm



19: Wing osf
Scratched
Over 25mm Thru Paint



20: Wheel osf
Scratched
Up To 50mm



21: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK