



46 Brampton Road  
Eastbourne  
BN229BN

01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**HN14ZXP**

## Skoda Octavia 1.4 TSI Elegance 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	21/08/2014	Body Style	Estate	MOT Due	20/08/2025
Year	2014	Keys	2	CAP Clean	£5,525.00
Mileage	79,791 Miles Warranted	Service history	Yes	CAP Average	£4,800.00
Fuel Type	Petrol	Service documents	Printout	CAP Below	£4,100.00
Colour	BLUE	Last service date	19/08/2024	Gearbox	SEMI AUTO
VIN	TMBKC7NEXF0017944	Last service miles	76,920	Gears	7

£100 ADDITIONAL FEE Last service 19/08/2024 @ 76920 miles (11 SERVICES 9 MAIN DEALER)

### Tyres

NSF	TRIANGLE	3.0mm
NSR	GT RADIAL	5.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Steering wheel mounted controls
- Digital radio
- Air conditioning
- Front head restraints
- Rear headrests
- Isofix child seat anchor points
- Central locking
- Cruise control
- Telephone
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Side airbags
- Leather seat trim
- Rear wiper
- Audio remote control
- Front fog lights
- Front electric windows
- Rear electric windows
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Dented  
With Paint Damage



4: Wheel nsf  
Scratched  
Over 50mm



5: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Wheel nsr  
Scratched  
Up To 50mm



10: Bumper Rear  
Scratched  
Over 100mm Thru Paint



11: Boot Lid  
Scratched  
Over 25mm Thru Paint



12: Wheel osr  
Scratched  
Up To 50mm



13: Qtr Panel osr  
Chipped  
1 To 5



14: Door osr  
Chipped  
1 To 5





15: Door osf  
Chipped  
Multiple Chips



16: Wheel osf  
Scratched  
Up To 50mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK