



# VEHICLE INSPECTION REPORT

**GV67GOU**

## Ford Kuga 2.0 TDCi Titanium 5dr 2WD

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/01/2018	Keys	2	CAP Clean	£6,000.00
Year	2018	Service history	Yes	CAP Average	£5,200.00
Mileage	83,850 Miles Warranted	Service documents	Service Book	CAP Below	£4,400.00
Fuel Type	Diesel	Number of stamps	6	Gearbox	MANUAL
Colour	WHITE	Last service date	28/07/2025	Gears	6
VIN	WF0AXXWPMJL42866	Last service miles	83,098	Doors	5
Body Style	Hatchback	MOT Due	30/01/2026		

£100 ADDITIONAL FEE

Last service 28/07/2025 at 83,098 miles- 6 services (3 main dealer)

### Tyres

NSF	BUDGET	5.0mm
NSR	MICHELIN	5.0mm
OSF	BUDGET	5.0mm
OSR	MICHELIN	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- Cruise control
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
1 To 5





3: Wheel nsf  
Scratched  
Up To 50mm

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



5: Door nsf  
Chipped  
Edge Chip



6: Door nsr  
Dented  
With Paint Damage



7: Qtr Panel nsr  
Scratched  
Up To 25mm Thru Paint



8: Wheel nsr  
Scratched  
Up To 50mm



9: Bumper Rear  
Dented  
Between 10mm + 30mm



10: Wheel osr  
Scratched  
Up To 50mm



11: Door osr  
Dented  
Between 10mm + 30mm



12: Wing osf  
Scratched  
UpTo 25mm Not Thru Paint



13: Roof  
Dented  
Over 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK