



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NY68UGC

Abarth 595 1.4 T-Jet 145 3dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	31/01/2019	Keys	2	CAP Clean	£6,975.00
Year	2019	Service history	Yes	CAP Average	£6,125.00
Mileage	49,393 Miles Warranted	Service documents	Service Book	CAP Below	£5,275.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	GREY	Last service date	29/06/2023	Gears	5
VIN	ZFA3120000JA94942	Last service miles	41,786	Doors	3
Body Style	Hatchback	MOT Due	28/06/2025		

£65 ADDITIONAL FEE Last service 29/06/2023 @ 41786 miles (5 SERVICES 4 MAIN DEALER)

Tyres

NSF	BUDGET	Damaged
NSR	YOKOHAMA	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- ABS
- Side airbags
- Remote central locking
- Cruise control
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Traction control
- Cloth seat trim
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Passenger airbag
- Central locking

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel osf
Scratched
Over 50mm



5: Wing osf
Poor Previous Repair
Poor Paint



6: Door osf
Chipped
1 To 5

No Image




7: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint


8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
Chipped
Multiple Chips



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint



11: Boot Lid
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Over 50mm




13: Qtr Panel nsr
Poor Previous Repair
Poor Paint



14: Sill Panel Trim ns
Broken
Replace



15: Door nsf
Chipped
1 To 5



16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Tyre nsf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK