



# VEHICLE INSPECTION REPORT

**DG69ENH**

## Seat Leon 1.5 TSI EVO 150 FR Black Edition [EZ] 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	19/02/2020	Keys	2	CAP Clean	£11,300.00
Year	2020	Service history	Yes	CAP Average	£10,200.00
Mileage	63,829 Miles Warranted	Service documents	Printout	CAP Below	£9,175.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	SEMI AUTO
Colour	RED	Last service date	24/11/2023	Gears	7
VIN	VSSZZZ5FZLR062531	Last service miles	35,050	Doors	5
Body Style	Hatchback	MOT Due	13/07/2026		

£65 ADDITIONAL FEE

Last service 24/11/2023 at 35,050 miles- 3 main dealer services

### Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	4.0mm
OSF	AVON	3.0mm
OSR	BRIDGESTONE	2.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Paint Flake





3: Wing nsf  
Poor Previous Repair  
Poor Paint




4: Wheel nsf  
Scratched  
Over 50mm



5: Door nsf  
Dented  
Over 2 UpTo 10mm



6: Door nsr  
Dented  
2 Or Less UpTo 10mm



7: Door nsr  
Scratched  
Over 25mm Not Thru Paint



8: Wheel nsr  
Scratched  
Up To 50mm



No Image

9: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



10: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

No Image

11: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



12: Boot Lid  
Dented  
Over 2 UpTo 10mm



13: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint




14: Door osr  
Chipped  
1 To 5

No Image

No Image

15: Door osr  
Scratched  
Over 25mm Not Thru Paint



16: Door osr  
Scratched  
Over 25mm Not Thru Paint



17: Door osf  
Chipped  
1 To 5



18: Wheel osr  
Scratched  
Up To 50mm



19: Wing osf  
Chipped  
1 To 5

20: Wheel osf  
Scratched  
Up To 50mm

## Interior



**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK