

46 Brampton Road Eastbourne BN229BN 01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KN15ZHZ

Mercedes-Benz C Class C200 Sport 4dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grade
		V5	Present		
Details					
Reg. date	31/03/2015	Body Style	Saloon	MOT Due	09/08/2025
Year	2015	Keys	2	CAP Clean	£8,400.00
Mileage	72,191 Miles Warranted	Service history	Yes	CAP Average	£7,425.00
		Service documents	Printout	CAP Below	£6,450.00
Fuel Type	Petrol	Last service date	30/08/2016	Doors	4
Colour	BLACK	Last service miles	23,572		
VIN	WDD2050422R049769				

£100 ADDITIONAL FEE Last service 30/08/2016 @ 23572 miles (2 MAIN DEALER SERVICES) Noise while revving

Tyres			
NSF	BUDGET	Worn	
NSR	BUDGET	3.0mm	
OSF	BUDGET	Worn	
OSR	BUDGET	4.0mm	
Spare			

Features

• Bluetooth connection

Rear parking sensor

- Digital radio
- Air conditioning
- · Front head restraints
- 3x3 point rear seat belts
- Isofix child seat anchor points
- · Remote central locking

- Cruise control Steering wheel mounted controls • Audio remote control
- Body coloured bumpers •
- Climate control
- Height adjustable drivers seat •
- ABŠ
- Passenger airbag ٠
- Leather seat trim

•

- · Front parking sensor
- Electric door mirrors ٠
- Front armrest
- · Rear electric windows
- Drivers airbag
- Traction control
- · Alloy wheels
- PAS
 - Auxiliary input socket
 - Front fog lights
 - Front electric windows
 - Solid Paint
 - ESP
- Central locking

Photos


















Condition Check



Damage Photos



No Image

1: Bumper Rear Poor Previous Repair Poor Paint

2: Boot Lid Scratched Over 25mm Not Thru Paint



No Image

3: Qtr Panel nsr Chipped 1 To 5



5: Wheel nsr Scratched Over 50mm



6: Door nsr Scratched Over 25mm Thru Paint

4: Qtr Panel nsr

Over 25mm Not Thru Paint

Scratched



7: Door nsf Dented With Paint Damage

No Image

8: Wing nsf Scratched Over 25mm Not Thru Paint




9: Bonnet Chipped Multiple Chips



11: Wheel nsf Scratched Over 50mm




10: Screen Front Chipped UpTo 10mm



12: Bumper Front Poor Previous Repair Poor Paint




13: Wheel osf Scratched Over 50mm



14: Door osf Chipped Multiple Chips

No Image

15: Door osr Scratched Over 25mm Not Thru Paint



16: Qtr Panel osr Dented 2 Or Less UpTo 10mm



No Image

17: Wheel osr Scratched Over 50mm 18: Tyre nsf Worn Replace

No Image

19: Tyre osf Worn Replace

Interior

Eastbourne Car Auctions

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK