



46 Brampton Road
Eastbourne
BN22 9BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LE16PFG

Mercedes-Benz C Class C220d Sport Premium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



Details

Reg. date	29/07/2016	Colour	GREY	MOT Due	20/05/2026
Year	2016	VIN	WDD2052042F413472	CAP Clean	£9,075.00
Mileage	70,716 Miles Warranted	Body Style	Estate	CAP Average	£8,000.00
Fuel Type	Diesel	Keys	2	CAP Below	£6,975.00

£65 ADDITIONAL FEES


Tyres


NSF	CONTINENTAL	Worn
NSR	GT RADIAL	4.0mm
OSF	CONTINENTAL	2.0mm
OSR	GT RADIAL	3.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- ABS
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Curtain airbags
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- 3x3 point rear seat belts
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Chipped
Multiple Chips



4: Bumper Front
Scratched
Over 25mm Not Thru Paint




5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Dented
Over 2 UpTo 10mm



7: Door nsf
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Chipped
1 To 5




10: Wheel nsr
Scratched
Up To 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Qtr Panel osr
Poor Previous Repair
Poor Paint



15: Wheel osr
Scratched
Over 50mm

No Image

16: Door osf
Scratched
Over 25mm Not Thru Paint




17: Door osf
Dented
Over 30mm



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Up To 50mm



20: Seat Base Cover osf
Torn
UpTo 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		