



VEHICLE INSPECTION REPORT

FM17BUU

Kia Sportage 1.7 CRDi ISG 2 5dr DCT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	04/07/2017	Keys	2	CAP Clean	£5,450.00
Year	2017	Service history	Yes	CAP Average	£4,725.00
Mileage	103,696 Miles Warranted	Service documents	Service Book	CAP Below	£4,025.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	SEMI AUTO
Colour	BLACK	Last service date	23/08/2024	Gears	7
VIN	U5YPH815VHL313494	Last service miles	87,636		
Body Style	Estate	MOT Due	10/01/2026		

£100 ADDITIONAL FEE.  
Last service 23/08/2024 at 87,636 miles- 8 services (2 main dealer)

Tyres		
NSF	BUDGET	4.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	4.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Cruise control
  - Rear parking sensor
  - Body coloured bumpers
  - Air conditioning
  - Front head restraints
  - Metallic Paint
  - ESP
  - Central locking
- Navigation system
  - Rear wiper
  - Electric door mirrors
  - Folding rear seats
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - Isofix child seat anchor points
  - Remote central locking
- Park assist camera
  - Steering wheel mounted controls
  - Front fog lights
  - Front armrest
  - Rear electric windows
  - ABS
  - Passenger airbag
  - Cloth seat trim
- PAS
  - Digital radio
  - Space saver spare wheel
  - Front electric windows
  - Rear headrests
  - Drivers airbag
  - Side airbags
  - Alloy wheels

Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Scratched  
Over 100mm Thru Paint





3: Wing nsf  
Scratched  
Over 25mm Thru Paint



4: Door nsf  
Scratched  
Over 25mm Thru Paint



5: Door nsr  
Dented  
With Paint Damage



6: Wheel nsr  
Scratched  
Over 50mm



7: Qtr Panel nsr  
Dented  
With Paint Damage



8: Bumper Rear  
Scratched  
Over 100mm Thru Paint





9: Bumper Rear Moulding  
Scuffed (Unpainted)  
Over 100mm



10: Tailgate  
Scratched  
Over 25mm Thru Paint



11: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



12: Door osr  
Scratched  
Over 25mm Thru Paint



13: Door osf  
Scratched  
Over 25mm Thru Paint



14: Wing osf  
Chipped  
Multiple Chips



15: Roof  
 Scratched  
 Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

**Disclaimer**  
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
 Additional fees may apply to some vendors.  
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK