



VEHICLE INSPECTION REPORT

DF16FME

Renault Captur 1.5 dCi 90 Dynamique S Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	22/07/2016	Keys	3	CAP Clean	£3,825.00
Year	2016	Service history	Yes	CAP Average	£3,250.00
Mileage	66,721 Miles Warranted	Service documents	Service Book	CAP Below	£2,675.00
Fuel Type	Diesel	Number of stamps	8	Gearbox	MANUAL
Colour	CREAM/BLACK	Last service date	23/09/2024	Gears	5
VIN	VF12RAJ1A55341251	Last service miles	60,973	Doors	5
Body Style	Hatchback	MOT Due	31/05/2026		

Last Service -23.09.2024 at 60973 miles (8 MAIN DEALER services) Service message displayed

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Side airbags
- Alloy wheels
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Cracked
UpTo 25mm



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Dented
Over 30mm



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Wheel nsr
Scratched
Over 50mm



8: Tailgate
Dented
Between 10mm + 30mm



9: Roof
Dented
Over 30mm



10: Wheel osr
Scratched
Over 50mm



11: Door osr
Chipped
Edge Chip




12: Door osf
Scratched
UpTo 25mm Thru Paint



13: Wing osf
Chipped
1 To 5



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK