



VEHICLE INSPECTION REPORT

WU12KWZ

Ford Mondeo 2.0 TDCi 140 Edge 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
5

Details

Reg. date	16/03/2012	Keys	1	CAP Clean	£880.00
Year	2012	Service history	Yes	CAP Average	£480.00
Mileage	153,153 Miles Warranted	Service documents	Service Book	CAP Below	£200.00
Fuel Type	Diesel	Number of stamps	15	Gearbox	MANUAL
Colour	SILVER	Last service date	26/08/2025	Gears	6
VIN	WF0GXXGBBGBP34696	Last service miles	152,925		
Body Style	Estate	MOT Due	Expired		

LAST SERVICE 26/8/25 @ 152,925 MILES (15 SERVICES) BOOK AND PRINT
MOT EXPIRED - TRANSPORTED OFF SITE Entertainment screen not working

Tyres


NSF	BUDGET	3.0mm
NSR	MATADOR	4.0mm
OSF	BUDGET	4.0mm
OSR	MATADOR	4.0mm
Spare		

Features


- Cruise control
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Steel wheels
- Rear wiper
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Steering wheel mounted controls
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
Over 100mm Thru Paint



2: Boot Lid
Dented
With Paint Damage



3: Qtr Panel nsr
Dented
With Paint Damage



4: Door nsr
Rusted
Over 5mm



5: Door nsf
Dented
With Paint Damage



6: Door Mirror Assy nsf
Broken
Replace



7: Wing nsf
Poor Previous Repair
Poor Paint



8: Bonnet
Chipped
Multiple Chips



9: Bumper Front
Cracked
UpTo 25mm



10: Bumper Front Grill
Broken
Replace



11: Wing osf
Dented
With Paint Damage



12: Door osf
Dented
With Paint Damage



13: Door osr
Dented
With Paint Damage



14: Qtr Panel osr
Dented
With Paint Damage



15: Handle Inner osf
Damaged
Replace

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	Fault
		Steering	OK