



VEHICLE INSPECTION REPORT

RO69KWV

Jeep Compass 1.6 Multijet 120 Limited 5dr [2WD]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	11/10/2019	VIN	MCANJPCS4KFA45059	CAP Clean	£8,300.00
Year	2019	Body Style	Estate	CAP Average	£7,250.00
Mileage	64,202 Miles Warranted	Keys	2	CAP Below	£6,175.00
Fuel Type	Diesel	Service history	None	Gearbox	MANUAL
Colour	RED/BLACK	MOT Due	Expired	Gears	6

No Service History EML LIGHT ON,CAR VIBRATES,ENGINE MISFIRE
STIFF GEARS

Tyres

NSF	COMPASSAL	Worn
NSR	WINDFORCE	3.0mm
OSF	COMPASSAL	Worn
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Traction control
- Leather seat trim
- Cruise control
- PAS
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- ESP
- Central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Solid Paint
- Passenger airbag
- Remote central locking

Photos






Condition Check



Damage Photos



1: Door osf
Dented
2 Or Less UpTo 10mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Dented
Over 2 UpTo 10mm



5: Door osr
Chipped
Edge Chip



6: Bumper Rear
Poor Previous Repair
Poor Paint



7: Wheel osf
Scratched
Over 50mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Door nsr
Dented
With Paint Damage




10: Wheel nsr
Scratched
Up To 50mm



11: Door nsf
Dented
Over 30mm



12: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Not Thru Paint




13: Wing nsf
Dented
Over 30mm




14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Bumper Front
Chipped
Multiple Chips



16: Tyre nsf
Worn
Replace



17: Tyre osf
Worn
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		