



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HY59LFO

Citroen C4 Grand Picasso 1.6HDi 16V VTR Plus 5dr EGS

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |

nama
GRADE
4

Details

| | | | | | |
|-----------|----------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 16/10/2009 | VIN | VF7UA9HZH9J260761 | CAP Average | £240.00 |
| Year | 2009 | Body Style | MPV | CAP Below | £200.00 |
| Mileage | 132,941 Miles Warranted | Keys | 2 | Gearbox | SEMI AUTO |
| Fuel Type | Diesel | MOT Due | 14/10/2025 | Gears | 6 |
| Colour | MAUVE/PURPLE | CAP Clean | £600.00 | | |

Vibration at idle and intermittent gearbox fault

Tyres

| | | |
|-------|------------|-------|
| NSF | BUDGET | 5.0mm |
| NSR | LANVIGATOR | 5.0mm |
| OSF | SAILUN | 3.0mm |
| OSR | LANVIGATOR | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Steering wheel mounted controls
- Radio/CD
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Telephone
- Body coloured bumpers
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Audio remote control
- Roof rails
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing osf
Scratched
Over 25mm Not Thru Paint



5: Wheel osf
Corroded
Light

6: Sill os
Rusted
Over 5mm



7: Door osf
Scratched
Over 25mm Thru Paint

8: Door osr
Chipped
1 To 5

No Image



9: Door osr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Poor Previous Repair
Poor Paint



11: Wheel osr
Scratched
Over 50mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint

No Image



13: Boot Lid
Scratched
Over 25mm Not Thru Paint

14: Qtr Panel nsr
Dented
With Paint Damage



15: Wheel nsr
Scratched
Over 50mm



16: Door nsr
Dented
With Paint Damage



17: Door nsf
Dented
Over 2 UpTo 10mm



18: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



19: Wing nsf
Chipped
1 To 5



20: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Poor

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|-------|--|----|
| Engine Runs | Fault | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |