



46 Brampton Road
Eastbourne
BN229BN

01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RJ13PXL

Volkswagen Golf 1.6 TDI 105 SE 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |

nama
GRADE
3

Details

| | | | | | |
|------------|-------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 05/07/2013 | Keys | 2 | CAP Clean | £3,325.00 |
| Year | 2013 | Service history | Yes | CAP Average | £2,775.00 |
| Mileage | 107,160 Miles Warranted | Service documents | Service Book | CAP Below | £2,250.00 |
| Fuel Type | Diesel | Number of stamps | 12 | Gearbox | MANUAL |
| Colour | SILVER | Last service date | 16/09/2024 | Gears | 5 |
| VIN | WVWZZZAUZEW019833 | Last service miles | 104,532 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 15/09/2025 | | |

£65 ADDITIONAL FEE Last service 16/09/2024 @ 104532 miles (12 SERVICES 1 MAIN DEALER)

Tyres



| | | |
|-------|---------|-------|
| NSF | PIRELLI | 4.0mm |
| NSR | PIRELLI | 4.0mm |
| OSF | PIRELLI | 5.0mm |
| OSR | PIRELLI | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Telephone
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- PAS
- Trip computer
- Electric door mirrors
- Front armrest
- Rear armrest
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Rear wiper
- Audio remote control
- Heated door mirrors
- Front electric windows
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Steering wheel mounted controls
- Radio/CD
- Air conditioning
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



4: Door osf
Chipped
1 To 5

3: Wheel osf
Scratched
Over 50mm

No Image

No Image

5: Door osr
Scratched
Over 25mm Not Thru Paint

6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Wheel osr
Scratched
Over 50mm




8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Boot Lid
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Door nsr
Chipped
1 To 5



13: Door nsf
Poor Previous Repair
Poor Paint



14: Wing nsf
Chipped
1 To 5



15: Wheel nsf
Scratched
Over 50mm

Interior

| | | | |
|------------------|---------|----------------------|---------|
| Carpet Condition | Average | Upholstery Condition | Average |
| Seat Condition | Average | Odour | No |

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Windows | OK | Radio | OK |
| | | Steering | OK |