



VEHICLE INSPECTION REPORT

EN62EVU

Hyundai I30 1.6 CRDi Blue Drive Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

nama
GRADE
3

Details

Reg. date	01/02/2013	VIN	TMAD251ULEJ086085	CAP Average	£1,825.00
Year	2013	Body Style	Hatchback	CAP Below	£1,400.00
Mileage	84,200 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	10/02/2026	Gears	6
Colour	SILVER	CAP Clean	£2,250.00	Doors	5

£65 ADDITIONAL FEE Exhaust smell inside cabin


Tyres


NSF	MICHELIN	4.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Cruise control
- Steering wheel mounted controls
- Radio/CD
- Climate control
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- PAS
- Telephone
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Audio remote control
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Cracked
UpTo 25mm



3: Wheel nsf
Scratched
Up To 50mm



4: Screen Front
Chipped
UpTo 10mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Sill ns
Dented
Over 30mm




7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Bumper Rear
Dented
With Paint Damage



10: Boot Lid
Scratched
Over 25mm Not Thru Paint




11: Qtr Panel osr
Dented
Between 10mm + 30mm



12: Wheel osr
Scratched
Over 50mm



13: Door osr
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Wing osf
Chipped
1 To 5

16: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK