



# VEHICLE INSPECTION REPORT

**GF17AGU**

## Vauxhall Mokka X 1.4T Active 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	31/03/2017	Keys	2	CAP Clean	£4,250.00
Year	2017	Service history	Yes	CAP Average	£3,650.00
Mileage	56,004 Miles Warranted	Service documents	Service Book	CAP Below	£3,050.00
Fuel Type	Petrol	Number of stamps	7	Gearbox	MANUAL
Colour	GREY	Last service date	03/05/2024	Gears	6
VIN	W0LJC7E84HB129036	Last service miles	46,819	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE Last service 03/05/2024 @ 46819 miles (7 MAIN DEALER SERVICES)

Front bumper misaligned

Slight tapping

### Tyres


NSF	BUDGET	4.0mm
NSR	CONTINENTAL	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Telephone
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear wiper
- Auxiliary input socket
- Roof rails
- Electrically adjustable passenger seat
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Steering wheel mounted controls
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips



No Image



3: Wing osf  
Scratched  
Over 25mm Not Thru Paint

4: Wheel osf  
Scratched  
Over 50mm



5: Door osr  
Chipped  
1 To 5

6: Wheel osr  
Corroded  
Light



7: Bumper Rear  
Scratched  
25 to 100mm Thru Paint

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Wheel nsr  
Corroded  
Light



10: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Door nsf  
Dented  
Over 2 UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK