



VEHICLE INSPECTION REPORT

GD17FXH

Kia Venga 1.6 4 5dr Auto [6]

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|---------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 23/05/2017 | Keys | 2 | CAP Clean | £8,150.00 |
| Year | 2017 | Service history | Yes | CAP Average | £7,175.00 |
| Mileage | 35,680 Miles Warranted | Service documents | Service Book | CAP Below | £6,200.00 |
| Fuel Type | Petrol | Number of stamps | 4 | Gearbox | AUTOMATIC |
| Colour | WHITE | Last service date | 31/05/2024 | Gears | 6 |
| VIN | U5YEH812MHL167204 | Last service miles | 34,906 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 22/05/2025 | | |

Last service 31/05/2024 @ 34906 miles (4 SERVICES 1 MAIN DEALER)

Tyres

| | | |
|-------|-------------|-------|
| NSF | CONTINENTAL | 3.0mm |
| NSR | CONTINENTAL | 5.0mm |
| OSF | CONTINENTAL | 3.0mm |
| OSR | CONTINENTAL | 3.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear parking sensor
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Digital radio
- Opening panoramic glass roof
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- Navigation system
- Steering wheel mounted controls
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Trip computer
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing osf
Chipped
1 To 5



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Over 50mm

No Image

9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

No Image

10: Door osf
Scratched
Over 25mm Not Thru Paint

No Image

11: Door nsf
Scratched
UpTo 25mm Not Thru Paint



12: Wheel nsf
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|---------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |