

## **VEHICLE INSPECTION REPORT**

**GY66DKO** 

## Toyota Verso 1.6 D-4D Icon TSS 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present	<u> </u>	
Details					
Reg. date	30/09/2016	Body Style	MPV	Last service miles	88,406
Year	2016	Keys	1	MOT Due	Expired
Mileage	105,865 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	6
Fuel Type	Diesel	Number of stamps	7		
Colour	WHITE	Last service date	19/09/2024		
VIN	NMTDM26R40R048555				

Last Service - 19.09.2024 at 88406 miles (7 services 5 main dealer services) MOT Expired Eml light is on Oil service warning message displayed

### **Tyres**

NSF	BUDGET	3.0mm	
NSR	AUTOGREEN	4.0mm	
OSF	RAPID	1.0mm	
OSR	BUDGET	5.0mm	
Spare			

### **Features**

- Bluetooth connection
- PAS
- · Body coloured bumpers
- Folding rear seats
- · Height adjustable drivers seat
- 3x3 point rear seat beltsESP
- · Side airbags
- · Alloy wheels

- Cruise control
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Isofix child seat anchor points
- Central locking


- Navigation system
- Steering wheel mounted controls Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- Curtain airbags
- Passenger airbag
- Remote central locking
- · Park assist camera
- Air conditioning
- Front head restraints
- Solid Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim

### **Photos**










# **Condition Check**



# **Damage Photos**



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched UpTo 25mm Thru Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Scratched UpTo 25mm Thru Paint



5: Door nsf Scratched UpTo 25mm Thru Paint



6: Door nsr Chipped Edge Chip



7: Bumper Rear Cracked UpTo 25mm



8: Qtr Panel osr Chipped 1 To 5



9: Door osr Scratched Over 25mm Thru Paint



10: Door osf Dented Between 10mm + 30mm



11: Wheel osf Scratched Up To 50mm



12: Wing osf Chipped 1 To 5



13: Roof Chipped 1 To 5



14: Screen Front Chipped UpTo 10mm

### Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition Odour** 

Average No

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK