



VEHICLE INSPECTION REPORT

GU14NZW

Ford Fiesta 1.0 EcoBoost Zetec 5dr

| Inspection | | Vehicle | |
|-----------------|----|---------|---------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | Present |



Details

| | | | | | |
|------------|------------------------|--------------------|--------------|-------------|-----------|
| Reg. date | 26/04/2014 | Keys | 2 | CAP Clean | £3,800.00 |
| Year | 2014 | Service history | Yes | CAP Average | £3,250.00 |
| Mileage | 42,444 Miles Warranted | Service documents | Service Book | CAP Below | £2,700.00 |
| Fuel Type | Petrol | Number of stamps | 10 | Gearbox | MANUAL |
| Colour | SILVER | Last service date | 24/04/2024 | Gears | 5 |
| VIN | WF0DXXGAKDES64560 | Last service miles | 38,486 | Doors | 5 |
| Body Style | Hatchback | MOT Due | 25/04/2026 | | |

Last Service - 24.04.2024 at 38486 miles (10 services)


Tyres

| | | |
|-------|----------|-------|
| NSF | NEXEN | 4.0mm |
| NSR | NEXEN | 6.0mm |
| OSF | NEXEN | 4.0mm |
| OSR | GOODYEAR | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Metallic Paint
- Traction control
- Alloy wheels
- Telephone
- Air conditioning
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip



3: Qtr Panel osr
Chipped
1 To 5




4: Wheel osf
Scratched
Over 50mm



5: Bumper Rear
Scratched
25 to 100mm Thru Paint




6: Bumper Rear
Chipped
Multiple Chips



7: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




8: Bumper Front
Chipped
Multiple Chips



9: Bonnet
Chipped
1 To 5



10: Bonnet
Dented
2 Or Less UpTo 10mm



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|----------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |