



# VEHICLE INSPECTION REPORT

**YS11KYK**

## Audi A5 2.0T FSI 180 Black Edition 2dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	23/06/2011	Keys	1	CAP Clean	£1,950.00
Year	2011	Service history	Yes	CAP Average	£1,675.00
Mileage	109,682 Miles Warranted	Service documents	Service Book	CAP Below	£1,375.00
Fuel Type	Petrol	Number of stamps	9	Gearbox	MANUAL
Colour	BLACK	Last service date	04/03/2021	Gears	6
VIN	WAUZZZ8T3BA088780	Last service miles	89,166		
Body Style	Coupe	MOT Due	25/11/2025		

Last Service - 04.03.2021 at 89166 miles (9 services)  
Slight knocking from front and engine slightly noisy

### Tyres

NSF	NANKANG	Worn
NSR	BRIDGESTONE	4.0mm
OSF	PIRELLI	3.0mm
OSR	MICHELIN	4.0mm
Spare		

## Features


- Bluetooth connection
- Service indicator
- Audio remote control
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Passenger airbag
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front armrest
- Rear armrest
- ABS
- Side airbags
- Leather seat trim
- PAS
- Telephone
- Radio/CD
- Heated door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- Isofix child seat anchor points
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




2: Bumper Rear  
Hole  
Over 25mm





3: Qtr Panel nsr  
Chipped  
1 To 5



4: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



5: Wheel nsr  
Scratched  
Over 50mm



6: Door nsf  
Chipped  
Multiple Chips



7: Wing nsf  
Dented  
Over 30mm



8: Screen Front  
Chipped  
UpTo 10mm



9: Bumper Front  
Poor Previous Repair  
Paint Flake



10: Bumper Front Moulding  
Broken  
Replace



11: Wheel nsf  
Scratched  
Over 50mm




12: Wing osf  
Dented  
Over 30mm



13: Wheel osf  
Scratched  
Over 50mm



14: Door osf  
Dented  
Over 30mm



15: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint

16: Tyre nsf  
Worn  
Replace

## Interior

**Carpet Condition**                      Average  
**Seat Condition**                      Average

**Upholstery Condition**              Average  
**Odour**                                      No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK