



VEHICLE INSPECTION REPORT

VE67CWP

Ford Focus 1.5 EcoBoost Titanium 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2018	Keys	2	CAP Clean	£6,575.00
Year	2018	Service history	Yes	CAP Average	£5,725.00
Mileage	64,403 Miles Warranted	Service documents	Service Book	CAP Below	£4,850.00
Fuel Type	Petrol	Number of stamps	6	Gearbox	AUTOMATIC
Colour	GREY	Last service date	12/10/2023	Gears	6
VIN	WF06XXGCC6HE64560	Last service miles	54,816		
Body Style	Estate	MOT Due	13/07/2025		

£65 ADDITIONAL FEE

Last Service - 12.10.2023 at 54816 miles (6 services)

Cambelt and Water-pump Replaced 17.07.2023 @ 53251 miles

Tyres

NSF	GOODYEAR	4.0mm
NSR	CONTINENTAL	3.0mm
OSF	GOODYEAR	4.0mm
OSR	CONTINENTAL	Worn

Spare


Features

- Bluetooth connection
- Rear wiper
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Electric door mirrors
- Front electric windows
- Rear headrests
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Passenger airbag
- Remote central locking

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Screen Front
Chipped
UpTo 10mm



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 2 UpTo 10mm



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm

No Image



9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint


10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Qtr Panel osr
Dented
2 Or Less UpTo 10mm




12: Door osr
Scratched
UpTo 25mm Thru Paint



13: Door osf
Chipped
1 To 5



14: Wheel osf
Scratched
Up To 50mm



15: Wheel osr
Scratched
Up To 50mm

16: Tyre osr
Worn
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK