



VEHICLE INSPECTION REPORT

ML08SSK

Mitsubishi Lancer 1.6 Equippe 4dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2008	Body Style	Saloon	Last service miles	56,150
Year	2008	Keys	3	MOT Due	14/05/2026
Mileage	90,313 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	4
Colour	SILVER	Number of stamps	7	Doors	4
VIN	JMASRCS3A7U000811	Last service date	25/10/2019		

LAST SERVICE 25/10/19 @ 56,150 MILES (7 SERVICES 6 MAIN DEALER) BOOK AND PRINT
MOT FAILURE IN 2025 Exhaust leak and intermittent starting fault


Tyres


NSF	LAUFENN	3.0mm
NSR	LAUFENN	4.0mm
OSF	LAUFENN	2.0mm
OSR	LAUFENN	4.0mm
Spare		

Features


- PAS
- Air conditioning
- Front head restraints
- Metallic Paint
- Remote central locking
- Radio/CD
- Climate control
- Height adjustable drivers seat
- Drivers airbag
- Cloth seat trim
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Passenger airbag
- Alloy wheels
- Electric door mirrors
- Front electric windows
- Rear headrests
- Central locking

Photos





Condition Check



Damage Photos



1: Roof
Rusted
Over 5mm



2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Poor Previous Repair
Poor Paint



4: Wing nsf
Poor Previous Repair
Poor Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 30mm



7: Door nsr
Poor Previous Repair
Poor Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Poor Previous Repair
Poor Paint




11: Reflector nsr
Missing
Replace



12: Qtr Panel osr
Dented
With Paint Damage



13: Boot Lid
Chipped
1 To 5



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Door osr
Dented
With Paint Damage



16: Wheel osr
Scratched
Over 50mm



17: Door osf
Dented
With Paint Damage



18: Wing osf
Dented
With Paint Damage



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK