



# VEHICLE INSPECTION REPORT

LO16NVZ

## Volkswagen Golf 1.6 TDI 110 Match Edition 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



### Details

Reg. date	14/06/2016	Keys	2	CAP Clean	£5,250.00
Year	2016	Service history	Yes	CAP Average	£4,525.00
Mileage	100,517 Miles Warranted	Service documents	Service Book	CAP Below	£3,800.00
Fuel Type	Diesel	Number of stamps	7	Gearbox	MANUAL
Colour	BLACK	Last service date	08/11/2024	Gears	5
VIN	WWWZZZAUZGW324826	Last service miles	94,530	Doors	5
Body Style	Hatchback	MOT Due	Expired		

£65 ADDITIONAL FEE  
Last Service - 08.11.2024 at 94530 miles (7 services)  
MOT EXPIRED Noisy engine



Tyres		
NSF	DAVANTI	4.0mm
NSR	DAVANTI	5.0mm
OSF	DAVANTI	4.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

## Features


- Bluetooth connection
  - PAS
  - Audio remote control
  - Front fog lights
  - Front electric windows
  - Rear headrests
  - Drivers airbag
  - Traction control
  - Alloy wheels
- Cruise control
  - Rear parking sensor
  - Digital radio
  - Air conditioning
  - Front head restraints
  - Solid Paint
  - Isofix child seat anchor points
  - Central locking
- Front parking sensor
  - Rear wiper
  - Body coloured bumpers
  - Climate control
  - Height adjustable drivers seat
  - 3x3 point rear seat belts
  - Passenger airbag
  - Remote central locking
- Navigation system
  - Steering wheel mounted controls
  - Electric door mirrors
  - Front armrest
  - Rear electric windows
  - ABS
  - Side airbags
  - Cloth seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Poor Previous Repair  
Poor Paint



3: Wheel nsf  
Scratched  
Over 50mm



4: Screen Front  
Chipped  
UpTo 10mm



5: Door nsf  
Poor Previous Repair  
Poor Paint



6: Door nsr  
Poor Previous Repair  
Poor Paint



7: Wheel nsr  
Scratched  
Over 50mm



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Bumper Rear  
Poor Previous Repair  
Poor Paint

No Image

10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm

No Image


12: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



13: Wheel osr  
Scratched  
Over 50mm



14: Door osr  
Chipped  
1 To 5



15: Door osf  
Chipped  
1 To 5



16: Wing osf  
Chipped  
Multiple Chips



17: Wheel osf  
Scratched  
Over 50mm

### Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK