



VEHICLE INSPECTION REPORT

HN14XZJ

Ford Fiesta 1.25 82 Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
2

Details

Reg. date	30/05/2014	Keys	2	CAP Clean	£4,750.00
Year	2014	Service history	Yes	CAP Average	£4,025.00
Mileage	27,693 Miles Warranted	Service documents	Service Book	CAP Below	£3,325.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	WHITE	Last service date	04/09/2020	Gears	5
VIN	WF0DXXGAKDEY21532	Last service miles	19,563	Doors	5
Body Style	Hatchback	MOT Due	02/06/2025		

£65 ADDITIONAL FEE

Last Service - 04.09.2020 at 19563 miles (3 services)

Tyres



NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front electric windows
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Cruise control
- Telephone
- Radio/CD
- Air conditioning
- Front head restraints
- ABS
- Traction control
- Alloy wheels
- PAS
- Trip computer
- Body coloured bumpers
- Climate control
- Rear headrests
- Drivers airbag
- Central locking
- Rear wiper
- Audio remote control
- Electric door mirrors
- Folding rear seats
- Solid Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips




2: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



3: Wheel nsr
Scratched
Over 50mm



4: Door nsr
Scratched
Over 25mm Not Thru Paint




5: Door nsf
Chipped
1 To 5



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wheel nsf
Scratched
Over 50mm




8: Screen Front
Chipped
UpTo 10mm



9: Bonnet
Chipped
1 To 5



10: Bumper Front
Scratched
25 to 100mm Thru Paint




11: Bumper Front
Scratched
Over 25mm Not Thru Paint




12: Wheel osf
Scratched
Over 50mm



13: Wing osf
Chipped
1 To 5



14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Door osr
Chipped
1 To 5

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Up To 50mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK