



VEHICLE INSPECTION REPORT

EO66JRV

Ford Focus 1.0 EcoBoost 125 Titanium 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	21/09/2016	Keys	2	CAP Clean	£4,150.00
Year	2016	Service history	Yes	CAP Average	£3,525.00
Mileage	53,137 Miles Warranted	Service documents	Service Book	CAP Below	£2,925.00
Fuel Type	Petrol	Number of stamps	3	Gearbox	MANUAL
Colour	BLACK	Last service date	07/12/2022	Gears	6
VIN	WF05XXGCC5GK27452	Last service miles	41,240	Doors	5
Body Style	Hatchback	MOT Due	25/09/2025		

£65 ADDITIONAL FEE

Last Service - 07.12.2022 at 41240 miles (3 services)

Tyres

NSF	JINYU TIRES	3.0mm
NSR	BUDGET	4.0mm
OSF	PIRELLI	2.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Lumbar support
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing osf
Chipped
Multiple Chips



4: Wheel osf
Scratched
Over 50mm



5: Screen Front
Chipped
UpTo 10mm



6: Door osf
Chipped
Multiple Chips



7: Door osr
Chipped
Multiple Chips




8: Wheel osr
Scratched
Over 50mm



9: Qtr Panel osr
Chipped
1 To 5



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Qtr Panel nsr
Chipped
1 To 5



13: Wheel nsr
Scratched
Over 50mm



14: Door nsr
Scratched
Over 25mm Thru Paint



15: Door nsf
Chipped
1 To 5



16: Wing nsf
Scratched
Over 25mm Thru Paint



17: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK