



VEHICLE INSPECTION REPORT

NA18KFX

Ford C-Max 1.0 EcoBoost Zetec 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/05/2018	Keys	2	CAP Clean	£3,875.00
Year	2018	Service history	Yes	CAP Average	£3,300.00
Mileage	65,425 Miles Warranted	Service documents	Service Book	CAP Below	£2,725.00
Fuel Type	Petrol	Number of stamps	5	Gearbox	MANUAL
Colour	BLACK	Last service date	10/03/2025	Gears	6
VIN	WF0VXXGCEVJY60271	Last service miles	63,441		
Body Style	MPV	MOT Due	30/03/2026		

£100 ADDITIONAL FEE

Last Service - 10.03.2025 at 63441 miles (5 services) Intermittent engine rattle

Tyres



NSF	HIFLY	2.0mm
NSR	GT RADIAL	2.0mm
OSF	HIFLY	2.0mm
OSR	GT RADIAL	2.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips



3: Wing osf
Dented
Over 30% Of Panel



4: Wheel osf
Scratched
Over 50mm



5: Door osf
Dented
Over 30% Of Panel



6: Door osr
Chipped
Multiple Chips



7: Qtr Panel osr
Dented
With Paint Damage



8: Wheel osr
Scratched
Over 50mm



9: Bumper Rear
 Scratched
 Over 100mm Thru Paint



10: Boot Lid
 Rusted
 Over 5mm



11: Qtr Panel nsr
 Dented
 With Paint Damage



12: Wheel nsr
 Corroded
 Light



13: Door nsr
 Dented
 With Paint Damage



14: Door nsr
 Dented
 With Paint Damage




15: Wing nsf
Dented
With Paint Damage



16: Wheel nsf
Scratched
Over 50mm



17: Screen Front
Chipped
UpTo 10mm



18: Bumper Front
Scratched
25 to 100mm Thru Paint

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK