



VEHICLE INSPECTION REPORT

YS19ZXL

Seat Arona 1.0 TSI SE Technology [EZ] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	16/03/2019	Keys	2	CAP Average	£7,175.00
Year	2019	Service history	Yes	CAP Below	£6,225.00
Mileage	46,603 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	Petrol	Last service date	15/06/2024	Gears	5
Colour	BLACK	Last service miles	40,133	Doors	5
VIN	VSSZZZKJZKR093715	MOT Due	15/03/2026		
Body Style	Hatchback	CAP Clean	£8,125.00		

£65 ADDITIONAL FEE Last service 15/06/2024 @ 40133 miles (5 MAIN DEALER SERVICES) Slight vibration at idle

Tyres

NSF	INVOVIC	4.0mm
NSR	RAPID	5.0mm
OSF	INVOVIC	3.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Folding rear seats
- Rear electric windows
- ABS
- Side airbags
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Cloth seat trim
- PAS
- Telephone
- Digital radio
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Wheel osf
Scratched
Over 50mm



4: Door osf
Dented
With Paint Damage



5: Door osr
Chipped
1 To 5



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint




7: Wheel osr
Scratched
Over 50mm



8: Boot Lid
Chipped
1 To 5



9: Bumper Rear
Chipped
Multiple Chips



10: Bumper Rear
Scratched
Over 25mm Not Thru Paint




11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Up To 50mm



13: Door nsr
Dented
Over 30mm



14: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image



15: Wing nsf
Scratched
Over 25mm Not Thru Paint

16: Wheel nsf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK