



VEHICLE INSPECTION REPORT

GY23FVM

Vauxhall Mokka 1.2 Turbo 100 GS 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	25/03/2023	Body Style	Hatchback	Last service miles	28,971
Year	2023	Keys	2	Gearbox	MANUAL
Mileage	37,194 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Petrol	Service documents	Service Book	Doors	5
Colour	BLACK	Number of stamps	2		
VIN	VXKUSHNEKPW008110	Last service date	26/03/2025		

£65 ADDITIONAL FEE

Last service 26/03/2025 at 28,971 miles- 2 services (1 main dealer)

Tyres

NSF	ROTALLA	5.0mm
NSR	ROTALLA	5.0mm
OSF	ROTALLA	5.0mm
OSR	ROTALLA	5.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wing nsf
Dented
Over 30mm



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Chipped
Edge Chip



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Chipped
1 To 5



8: Bumper Rear
Scratched
25 to 100mm Thru Paint



9: Qtr Panel osr
Dented
With Paint Damage




10: Door osr
Scratched
UpTo 25mm Thru Paint



11: Door osf
Chipped
Edge Chip



12: Wing osf
Scratched
UpTo 25mm Thru Paint



13: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK