



# VEHICLE INSPECTION REPORT

NA64ACV

## BMW M6 M6 4dr DCT

### Inspection

Serious Damage? No

### Vehicle

VAT Margin

V5 Present

nama  
GRADE  
3

### Details

Reg. date 30/09/2014

Year 2014

Mileage 94,652 Miles  
Warranted

Fuel Type Petrol

Colour BLUE

VIN WBS6C92090D879227

Body Style Coupe

Service history Yes

Service documents Printout

Number of stamps 5

Last service date 29/08/2025

Last service miles 93,767

MOT Due Expired

Gearbox AUTOMATIC

Gears 7

£100 ADDITIONAL FEE

Last service 29/08/2025 at 93,767 miles- 5 services (2 main dealer)

Service in 2025 recorded as 150,903km Engine noisy while revving

### Tyres

NSF MICHELIN 4.0mm

NSR MICHELIN 4.0mm

OSF MICHELIN 4.0mm

OSR MICHELIN 4.0mm


Spare

### Photos






## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips

No Image



3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint


4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door nsf  
Chipped  
1 To 5

No Image

8: Door nsf  
Scratched  
Over 25mm Not Thru Paint



9: Door nsr  
Poor Previous Repair  
Poor Paint




10: Wheel nsr  
Scratched  
Over 50mm




11: Qtr Panel nsr  
Poor Previous Repair  
Poor Paint



12: Bumper Rear  
Chipped  
Multiple Chips



13: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



14: Boot Lid  
Scratched  
Over 25mm Not Thru Paint

No Image




15: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint

16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Chipped  
1 To 5

18: Door osr  
Scratched  
Over 25mm Not Thru Paint



19: Door osf  
Chipped  
1 To 5

20: Door osf  
Scratched  
Over 25mm Not Thru Paint




21: Wing osf  
Chipped  
1 To 5



22: Wheel osf  
Scratched  
Over 50mm



23: Screen Front  
Chipped  
UpTo 10mm



24: Seat Base Cover osf  
Scuffed  
UpTo 25mm

### Interior

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      No

### Vehicle Inspection Report

**Disclaimer**  
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.  
Additional fees may apply to some vendors.  
Please note buyers rate increase from 01/01/2025

|                |       |                                                |    |
|----------------|-------|------------------------------------------------|----|
| Engine Runs    | Fault | Gearbox 1st and Reverse Test                   | OK |
| Brakes         | OK    | Clutch Slip Test from Static                   | OK |
| Turbo Boosting | OK    | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake  | OK    | No Excessive Smoking                           | OK |

|                          |    |                                     |    |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated    | OK | Oil warning light illuminated       | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated    | OK |                                     |    |
| Windows                  | OK | Radio                               | OK |
| Sat nav                  | OK | Steering                            | OK |