



VEHICLE INSPECTION REPORT

GU62URH

Volvo XC90 2.4 D5 [200] SE 5dr Geartronic

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	06/10/2012	Body Style	Estate	Last service miles	148,757
Year	2012	Keys	2	MOT Due	05/10/2026
Mileage	158,788 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	13		
VIN	YV1CZ3056C1639850	Last service date	25/09/2024		

£65 ADDITIONAL FEE

Last service 25/09/2024 at 148,757 miles- 13 main dealer services Gearbox clicking while changing gears
Service overdue message displayed

Tyres


NSF	GOODYEAR	5.0mm
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Cruise control
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- PAS
- Radio/CD
- Roof rails
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Dented
Between 10mm + 30mm



6: Door nsf
Scratched
UpTo 25mm Thru Paint



7: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door Moulding nsr
Scratched (Painted)
Over 25mm Thru Paint



9: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Tailgate
Scratched
UpTo 25mm Thru Paint



12: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
2 Or Less UpTo 10mm



17: Wing osf
Scratched
Over 25mm Thru Paint



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK