



VEHICLE INSPECTION REPORT

HY08NWD

Volkswagen Tiguan 2.0 TDi SE 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	01/03/2008	Body Style	Estate	Last service miles	66,435
Year	2008	Keys	1	MOT Due	Expired
Mileage	85,621 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	12		
VIN	WVGZZZ5NZ8W015735	Last service date	28/11/2020		

EXPIRED MOT.

Last Service - 28.11.2020 at 66435 miles (12 services)

Heater blowers not working

Roof lining dropped

EML light on

Engine tappy

Cars in limp mode

Low clutch

Tyres



NSF	BUDGET	Worn
NSR	RAPID	4.0mm
OSF	BUDGET	Worn
OSR	RAPID	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Climate control
- Rear electric windows
- ABS
- Central locking
- Audio remote control
- Electric sunroof
- Front electric windows
- Rear headrests
- Drivers airbag
- Remote central locking
- Digital radio
- Fixed panoramic glass roof
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Roof Lining
Torn
Over 3mm



2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips




4: Bumper Front
Poor Previous Repair
Paint Flake



5: Bumper Front Grill
Broken
Replace



6: Wing nsf
Dented
Between 10mm + 30mm



7: Wing nsf
Scratched
Over 25mm Not Thru Paint



8: Wheel nsf
Scratched
Over 50mm



9: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



10: Door nsf
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage



12: Wheel nsr
Scratched
Up To 50mm



13: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




14: Lamp nsr
Broken
Replace



15: Bumper Rear
Dented
With Paint Damage



16: Boot Lid
Chipped
1 To 5



17: Boot Lid
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel osr
Dented
Over 30mm



19: Wheel osr
Scratched
Up To 50mm




20: Door osr
Dented
With Paint Damage



21: Door osf
Dented
With Paint Damage



22: Wing osf
Chipped
1 To 5



23: Wing osf
Scratched
Over 25mm Not Thru Paint



24: Wheel osf
Scratched
Up To 50mm



25: A Post os
Rusted
UpTo 5mm



26: Screen Front
Chipped
UpTo 10mm



27: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK