

VEHICLE INSPECTION REPORT



Mercedes-Benz E Class E 200 AMG Line Premium 5dr 9G-Tronic

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Buyer To Apply		
Details					
Reg. date	19/03/2019	VIN	WDD2132422A535713	Number of stamps	6
Year	2019	Body Style	Estate	Last service date	24/02/2025
Mileage	97,639 Miles	Keys	1	Last service miles	92,292
	Warranted	Service history	Yes	MOT Due	18/03/2026
Fuel Type	Petrol	Service documents	Printout	-	
Colour	BLACK				

£65 ADDITIONAL FEE. No V5. Last service 24/02/2025 at 92292 miles (6 main dealer services). Eml on and rough running

1/	Δ	•
v	ᆫ	J

Spare			
OSR	BUDGET	4.0mm	·
OSF	APOLLO	4.0mm	
NSR	TRIANGLE	4.0mm	
NSF	TRIANGLE	4.0mm	

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- · Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- · Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- Climate control
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim
- · Front parking sensor
- PAS
- Electric sunroof
- · Front head restraints
- Rear headrests
- Curtain airbags Traction control
- · Alloy wheels

- · Heated front seat
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable drivers seat Electrically adjustable passenger seat
 - Height adjustable drivers seat
 - Solid Paint
 - Drivers airbag
 - Central locking

Photos











THE PROPERTY OF

Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched Over 100mm Thru Paint




3: Wheel nsf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5

No Image

5: Wing nsf Scratched Over 25mm Not Thru Paint



6: Screen Front Chipped UpTo 10mm



7: Door nsf Dented With Paint Damage



8: Door nsr Dented With Paint Damage




9: Wheel nsr Scratched Over 50mm



10: Qtr Panel nsr Dented Over 2 UpTo 10mm

No Image





12: Bumper Rear Scratched Over 100mm Thru Paint



13: Boot Lid Chipped 1 To 5

No Image

14: Boot Lid Scratched Over 25mm Not Thru Paint



15: Qtr Panel osr Poor Previous Repair Poor Paint



16: Wheel osr Scratched Over 50mm



17: Door osr Poor Previous Repair Poor Paint



18: Door osf Dented With Paint Damage



19: Wing osf Chipped 1 To 5

No Image

20: Wing osf Scratched Over 25mm Not Thru Paint



21: Wheel osf Scratched Over 50mm



22: Wiper Rear Broken Replace

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaime

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		