



VEHICLE INSPECTION REPORT

GY71JWO

MG Mg 5 EXCLUSIVE

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
4

Details

Reg. date 18/10/2021

Year 2021

Mileage 62,768 Miles
Warranted

Fuel Type Electric

Colour BLACK

VIN LSJE24094LG097395

Body Style Estate

Keys 2

MOT Due Expired

Gearbox AUTOMATIC

Gears 1

EXPIRED MOT. £100 ADDITIONAL FEE. No charging cables

Tyres

NSF BUDGET Worn

NSR BRIDGESTONE Worn

OSF BUDGET 3.0mm

OSR BRIDGESTONE 4.0mm


Spare

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Fog Lamp Surrounds
Broken
Replace



3: Bonnet
Chipped
Multiple Chips



4: Wheel osf
Scratched
Over 50mm



5: Wing osf
Chipped
1 To 5



6: Wing osf
Scratched
Over 25mm Not Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door osr
Dented
With Paint Damage




9: Qtr Panel osr
Dented
With Paint Damage



10: Wheel osr
Scratched
Up To 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Boot Lid
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel nsr
Dented
Over 30mm



16: Wheel nsr
Scratched
Up To 50mm




17: Door nsr
Dented
With Paint Damage



18: Door nsf
Chipped
Multiple Chips



19: Wing nsf
Chipped
1 To 5



20: Wing nsf
Scratched
Over 25mm Not Thru Paint



21: Wheel nsf
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK