



VEHICLE INSPECTION REPORT

GJ12YCB

Audi A1 1.4 TFSI Sport 3dr

nama
 GRADE
3

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC

Details

Reg. date	30/03/2012	VIN	WAUZZZ8X4CB219956	CAP Average	£1,825.00
Year	2012	Body Style	Hatchback	CAP Below	£1,375.00
Mileage	129,199 Miles Warranted	Keys	2	Gearbox	MANUAL
Fuel Type	Petrol	MOT Due	27/01/2026	Gears	6
Colour	WHITE	CAP Clean	£2,275.00	Doors	3

Slight vibration and possible exhaust leak.
 Noise while pulling away and brakes noise
 Possible suspension knock

Tyres

NSF	BUDGET	4.0mm
NSR	KORMORAN	Damaged
OSF	KORMORAN	4.0mm
OSR	KORMORAN	4.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Body coloured bumpers
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- Trip computer
- Electric door mirrors
- Front armrest
- Rear headrests
- ABS
- Central locking
- PAS
- Audio remote control
- Heated door mirrors
- Front electric windows
- Steering wheel rake adjustment
- Drivers airbag
- Remote central locking
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Partial leather seat trim

Photos





Condition Check



Damage Photos




1: Qtr Panel nsr
Dented
With Paint Damage



2: Wheel nsr
Scratched
Over 50mm



3: Door nsf
Chipped
1 To 5



4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Screen Front
Chipped
UpTo 10mm



7: Bonnet
Chipped
1 To 5




8: Bumper Front
Scratched
Over 100mm Thru Paint



9: Wing osf
Scratched
Over 25mm Thru Paint



10: Wheel osf
Scratched
Over 50mm



11: Door osf
Scratched
Over 25mm Not Thru Paint



12: Door osf
Chipped
1 To 5



13: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



14: Wheel osr
Scratched
Over 50mm




15: Bumper Rear
Chipped
Multiple Chips



16: Boot Lid
Chipped
1 To 5



17: Wiper Rear
Broken
Replace



18: Tyre nsr
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK