



VEHICLE INSPECTION REPORT

KN12UBW

Kia Sportage 2.0 CRDi KX-2 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2012	Body Style	Estate	Last service miles	66,739
Year	2012	Keys	2	MOT Due	12/02/2026
Mileage	70,823 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	8		
VIN	U5YPC813NCL141469	Last service date	12/06/2023		

Last Service - 12.06.2023 at 66739 miles (8 services)

High clutch and tapping engine

Sun roof faulty

Missing two rear head rests

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Curtain airbags
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Solid Paint
- Drivers airbag
- Central locking
- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Partial leather seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: Door nsf
Dented
With Paint Damage




7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Chipped
1 To 5




10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Dented
Over 2 UpTo 10mm

No Image

15: Boot Lid
Scratched
Over 25mm Not Thru Paint



16: Qtr Panel osr
Chipped
1 To 5

No Image

17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Over 50mm



19: Door osr
Dented
With Paint Damage



20: Door osf
Dented
Over 2 UpTo 10mm



21: Door osf
Chipped
1 To 5



22: Wing osf
Dented
With Paint Damage



23: Screen Front
Chipped
UpTo 10mm



24: Wheel osf
Scratched
Over 50mm



25: A Post os
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK