

VEHICLE INSPECTION REPORT

GJ71MKF

BMW X5 xDrive30d MHT xLine 5dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		Grape Grape
		V5	TBC	•	
Details					
Reg. date	19/02/2022	VIN	WBAJU820909J30498	CAP Average	£35,200.00
Year	2022	Body Style	Estate	CAP Below	£34,000.00
Mileage	25,625 Miles Warranted	Keys	2	Gearbox	AUTOMATIC
		MOT Due	13/01/2026	Gears	8
Fuel Type	Electric Diesel	CAP Clean	£36,500.00		
Colour	BLUE				

£65 ADDITIONAL FEE

_			
У	r	е	S

NSF	HANKOOK	2.0mm
NSR	BUDGET	Worn
OSF	HANKOOK	2.0mm
OSR	HANKOOK	Worn
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper Audio remote control
- Electric door mirrors
- Opening panoramic glass roof
- Electrically adjustable drivers seat Electrically adjustable passenger Front armrest
- Front head restraints
- · Rear headrests
- 3x3 point rear seat beltsESP
- Tyre pressure monitor
- Alloy wheels

- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Electric sunroof
- Roof rails
- seat
- Height adjustable drivers seat Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

- · Front parking sensor
- PAS
- Telephone
- Digital radioFront fog lightsAir conditioning

- · Rear armrest
- Curtain airbags
- Passenger airbag
- Remote central locking


- · Heated front seat
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Heated door mirrors
- Climate control
- · Front electric windows
- Rear electric windows
- Drivers airbag Traction control
- · Leather seat trim

Photos












Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5 No Image

2: Bumper Front Scratched Over 25mm Not Thru Paint



3: Bumper Front Chipped Multiple Chips




4: Wing osf Chipped 1 To 5



5: Wheel osf Scratched Up To 50mm



6: Door osf Chipped 1 To 5



7: Door osr Chipped 1 To 5



8: Wheel osr Scratched Over 50mm

No Image

9: Bumper Rear Scratched Over 25mm Not Thru Paint



11: Qtr Panel nsr Scratched Over 25mm Thru Paint



13: Door nsr Scratched Over 25mm Thru Paint



10: Boot Lid Chipped 1 To 5



12: Wheel nsr Scratched Over 50mm




14: Door nsf Chipped 1 To 5

No Image

No Image

15: Door nsf Scratched UpTo 25mm Not Thru Paint





17: Wheel nsf Scratched Over 50mm

No Image

18: Screen Front Chipped UpTo 10mm

No Image

No Image

19: Tyre nsr Worn Replace 20: Tyre osr Worn Replace

No Image



22:

21: Other N/A N/A

No Image

No Image

23: Tyre nsr Worn Replace 24: Tyre osr Worn Replace

Interior

Carpet Condition OK **Seat Condition** OK

Upholstery Condition OK **Odour** No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs Of	Gearbox 1st and Reverse Test OK
Brakes OF	Clutch Slip Test from Static OK
Turbo Boosting Of	Gearbox Static Gear Selection (engine running) OK
Parking Brake Oh	No Excessive Smoking OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		